## **TOSHIBA**

### SERVICE MANUAL

# **COLOR TELEVISION**

**NOES Chassis** 

32A30 (TAC0009)

#### - SUMMARY -

32A30 is the same as 32A50 except for the parts tabled on back of this sheet. Use this service manual together with the service manual of 32A50 (File No. 020-200014).

#### REPLACEMENT PARTS LIST DIFFERENCES

Location No.	Part No.	Description
A201	23510250	Front Cover
A411	23427247	Back Cover
A703	23935701	Packing, Top
A708	23935702	Packing, Bottom
CV03	24232103	CD, 0.01μF, +80%, -20%
CZ01	24797478	EL, 0.47 µF, ±20%, 50V
CZ02	24794101	EL, 100μF, ±20%, 16V
CZ03	24092398	CD, 0.1µF, +80%, -20%, 25V
CZ04	24476103	CD, 0.01µF, ±30%, 16V
CZ05	24476103	CD, 0.01μF, ±30%, 16V
CZ06	24476103	CD, 0.01μF, ±30%, 16V
CZ07	24794101	EL, 100μF, ±20%, 16V
CZ08	24092398	CD, 0.1µF, +80%, -20%, 25V
CZ09	24567103	PF, 0.01μF
CZ10	24436220	CD, 22pF
CZ11	24567103	PF, 0.01μF
CZ12	24474181	CD, 180pF, ±10%
CZ13	24476103	CD, 0.01μF, ±30%, 16V
CZ14	24476103	CD, 0.01μF, ±30%, 16V
CZ15	24473560	CD, 56pF
CZ16	24473470	CD, 47pF
CZ18	24092398	CD, 0.1µF, +80%, -20%, 25V
CZ19	24794330	EL, 33μF, ±20%, 16V
CZ21	24366750	CF, 75 ohm
CZ23	24092398	CD, 0.1µF, +80%, -20%, 25V
CZ24	24436151	CD, 150p
K912	23306309	Remote Hand Unit, CT-9988
LZ01	23289330	Coil, Peaking, TRF4330AF
LZ02	23103880	Coil (Ferrite Bead), TEM2011Y
LZ04	23103880	Coil (Ferrite Bead), TEM2011Y
1		

Location No.	Part No.	Description
LZ05	23289100	Coil, Peaking, TRF4100AF
LZ06	23289270	Coil, Peaking, TRF4270AF
LZ07	24366101	CF, 100 ohm
LZ11	23289836	Coil, Peaking, TRF42R2AT
PZ01	23368006	Plug, 8P
PZ01A	23902743	Socket, 8P
Q503	23114528	Transistor, 2SC1740S, Q
QZ01	23906207	IC, TC90A45P
QZ02	23114528	Transistor, 2SC1740S, Q
QZ03	23114528	200
QZ04	23114528	Transistor, 2SC1740S, Q
R201	24366102	CF, 1k ohm
R202	24366102	CF, 1k ohm
R508		CF, 1k ohm
R509	24366102	CF, 1k ohm
R510	24366471	CF, 470 ohm
RZ01	24366101	CF, 100 ohm
RZ02	24366221	CF, 220 ohm
RZ03		CF, 1k ohm
RZ04	24366102	CF, 1k ohm
RZ05	24366821	CF, 820 ohm
RZ08	24366102	CF, 1k ohm
RZ30	24366102	CF, 1k ohm
* U902		Main Board, PB9399I
* UZ01		DIG COM Board, PB8689
Y101	23563965	Owner's Manual, English, 32A30
Y101F	23563968	Owner's Manual, French, 32A30
1		

#### **TOSHIBA CORPORATION**

1-1, SHIBAURA 1-CHOME, MINATO-KU, TOKYO 105-8001, JAPAN